A EVALUATION	Tay					INED	e despois de la compansión de la compans	The same and the s		in a since of the same				
DATE OF CONT	7													
DATE OBTAINE	0	Miller Gree, Yalussussens old y Redictablesens, y		agininasy 1944 and 1854 and 1854	Statement delta	JATE PI								
REFERENCES_													-	
AGES	ï													
REMARKS														-
		ka pempelakatakapan peper peper peper pe												
or and them, producted the COV while a set subspects.	MACHEMATICAL AND											****	*****	anzenne n
ar aradic passas supplementativos del color o currente del color o curre			LITERA SE SECONO LABORATORIO	a unangian Marana atau	region discrete de resper ; de 170	10-0 car 2000 Accessor.			likkus serun says m	97 S. SEC. SEC. SEC. SEC. SEC. SEC. SEC. S	*********	***************************************		40°C - 80°C

2

25X1A

- 1. In January 1953, source observed that work was in progress in the extensions of the runway at Mahlwinkel airfield. The cut timber was being cleared away and the last trees were being cut. No construction material or runway mats were observed arriving at the field up to 3 February.
- 2. Most of the narrow-gauge field railway tracks which extended from Tangerhuette to the field were being shipped away in January. A small portion of ties and rails were still stored in the vicinity of the field in early February.
- 3. About 30 laborers and construction superintendent Blaurock (fnu) were employed at the field up to 3 February. They were to be transferred to Berlin on 7 February for construction work on the railway bypass, where one Klingenberg (fnu) allegedly was the construction superintendent. Blaurock was to assist Klingenberg. The former Russian billets were still guarded by two civilians from Mahlwinkel.
- 4. On 1 February, a construction worker said that he believed that the soil at the field will never become solid. He further stated that impowement work was carried out in accordance with the Soviet orders although the Bauunion had repeatedly expressed great doubt as to the efficiency of the construction method.

Completed in early February 1953. There were no indications that steps have been taken to render the surface of the landing field more solid.

CLASSIFICATION SECRET,